

Earth connecting boxes



A safe earth bonding point with our earthing components in your ESD area

Due to the great variety of bonding possibilities, we only listed the most common types.

Should you require other bonding solutions we are pleased to receive your enquiry.

Attention:
explanation of accessory signs

SB = safety laboratory jack
DK 10 = snap fastener
MC = pin panel outlet



Barrier strip box
Includes a metal strip with 6 screws which allows 6 wires with a 4 mm ring to be connected to an earth bonding point.

Order No: 38.301.45



With safety resistor - includes 1 connection via coiled cord and derivation via safety plug.

| Order No: | Snap fastener size |
|-----------|--------------------|
| 38.301.01 | 10 mm |
| 38.301.02 | 4 mm |



With earthing plug for connecting earthed socket connections 6xDK 10.

Order No: 38.301.20



Suitable for installation on or under the table, flanch mounting, connections 2 x SB, 2 x DK 10

Order No: 38.301.21



For screw mounting on or under the table; connections 1 x MC, 2 x DK 10

Order No: 38.301.22



For screw mounting on or under the table; connections 2 x SB, 2 x DK 10

Order No: 38.301.23



For screw mounting on or under the table; connections 3 x DK 10

Order No: 38.301.24



For screw mounting on or under the table; connections 1 x MC, 1 x SB, 1 x DK 10

Order No: 38.301.25



For screw mounting on or under the table; connections 1 x SB, 2 x DK 10

Order No: 38.301.04



For screw mounting on or under the table.

| Order No: | Design |
|-----------|-------------------|
| 38.301.27 | 2 x SB, 1 X DK 10 |
| 38.301.28 | 2 x MC, 1 X DK 10 |



For screw mounting on or under the table.

| Order No: | Design |
|-----------|--------|
| 38.301.29 | 3 x SB |
| 38.301.30 | 3 x MC |



For screw mounting on or under the table.

| Order No: | Design |
|-----------|-----------|
| 38.301.31 | 4 x DK 10 |
| 38.301.32 | 4 x SB |
| 38.301.33 | 4 x MC |